

# PAT Report Passes For all Sites and Locations



**CLIENT DETAILS**

Company Name: Tangerine Events Ltd

Address: 1 Hampton Road  
Twickenham  
Middlesex  
TW2 5QE

**DETAIL OF CONTRACTOR RESPONSIBLE FOR TESTING**

Company Name: Abracadabra Sound & Light

Address: 314 Nelson Road  
Whitton  
Middlesex  
TW2 7AH

Telephone: 020 8893 3313

Mobile: 07860 465769

Email: pattesting@abra.co.uk

Cert Number: 1-031101

Signature:

Order Number:

File Name: Download 12 January 2024 10-54

**PAT TESTER DETAILS**

Serial Number	Make and Model	Certificate Number	Calibration Due Date
31C-0976			

**APPLIANCE DETAILS AND TEST RESULTS**

Key  
P = PASS / F = FAIL / S = SKIP (or test not applicable)

Appliance Id	Appliance Description	Test Date	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (kVA)	Leakage (mA)	Overall Status
<b>ABRACADABRA - OFFICE</b>									
01626	IEC LEAD	21/11/23	P	P	P 0.04	P >99.99	S	S	PASS
01627	MIER	21/11/23	P	S	P 0.09	P >99.99	P <0.05	P 0.57	PASS
01628	IEAR5	21/11/23	P	S	P 0.09	P >99.99	P 0.11	P 0.20	PASS
01629	ASS I	21/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01630	TOP	21/11/23	P	S	P 0.09	P >99.99	P 0.12	P 0.20	PASS
01632	SU	21/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01633	SU	21/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01634	IGHT AR	21/11/23	P	S	P 0.08	P >99.99	P 0.08	P 0.19	PASS
01635	MOIG HEAD AR	21/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01636	MOIG HEAD AR	21/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01638	YOP	21/11/23	P	S	P 0.08	P >99.99	P 0.10	P 0.19	PASS
01639	MOIG HEAD AR	21/11/23	P	S	P 0.08	P >99.99	P 0.20	P 0.31	PASS
01640	MOIG HEAD AR	21/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01641	DOT AR	21/11/23	P	S	P 0.08	P >99.99	P 0.13	P 0.18	PASS
01643	IEAR 115 FA	22/11/23	P	S	P 0.08	P >99.99	P 0.10	P 0.20	PASS
01644	ASS I	22/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01645	ASS I	22/11/23	P	S	P 0.08	P 70.13	P <0.05	P <0.10	PASS
01646	ASS I	22/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01647	ASS	22/11/23	P	S	P 0.10	P 54.04	P <0.05	P <0.10	PASS

**APPLIANCE DETAILS AND TEST RESULTS**

**Key**  
P = PASS / F = FAIL / S = SKIP (or test not applicable)

Appliance Id	Appliance Description	Test Date	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (kVA)	Leakage (mA)	Overall Status
01648	EUME8 KUDOS	22/11/23	P	S	P 0.09	P >99.99	P 0.16	P 0.50	PASS
01649	EUME8 KUDIS 700	22/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01650	MOIG HEAD AR	22/11/23	P	S	P 0.08	P >99.99	P 0.17	P 0.28	PASS
01651	HAE MAHIE	22/11/23	P	S	P 0.09	P >99.99	P 1.73	P <0.10	PASS
01652	ORE PAR4	22/11/23	P	S	P 0.10	P >99.99	P 0.08	P 0.34	PASS
01653	MOIG HEAG AR	22/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01654	HK SU	22/11/23	P	S	P 0.08	P >99.99	P 0.11	P 0.24	PASS
01655	HK TOP	22/11/23	P	S	P 0.08	P >99.99	P 0.11	P 0.14	PASS
01656	HK SU	22/11/23	P	S	P 0.09	P >99.99	P 0.11	P 0.24	PASS
01657	HK SU	22/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01658	HK TOP	22/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01659	EUME8	22/11/23	P	S	P 0.09	P >99.99	P <0.05	P <0.10	PASS
01660	EUME8 KUDOS 7000	22/11/23	P	S	P 0.09	P >99.99	P 0.15	P 0.48	PASS
01661	HK SU	22/11/23	P	S	P 0.08	P >99.99	P <0.05	P <0.10	PASS
01662	QU16	22/11/23	P	S	P 0.09	P >99.99	P 0.05	P 0.58	PASS

Total Appliances > **34**

**Total Appliances For Report: 34**